

E.H. Wachs 600 Knightsbridge Parkway Lincolnshire, IL 60069 www.ehwachs.com

Large Diameter Split Frame (LDSF) User's Manual



E.H. Wachs Part No. 12-042-MAN Rev. A, July 2013

Revision History: Original July 2013

> Copyright © 2013 E.H. Wachs. All rights reserved. This manual may not be reproduced in whole or in part without the written consent of E.H. Wachs.

Chapter 3 Operating Instructions

SAFE OPERATION OF THE LDSF

The LDSF has dangerous pinch points between rotating and stationary components. DO NOT STAND CLOSE TO THE MACHINE WHILE IT IS OPERATING. SERIOUS INJURY COULD RESULT.

Use of the counterbore slide requires the operator to feed the slide manually while the LSDF rotates. **THIS SHOULD BE DONE ONLY WITH THE LDSF MOUNTED ON A HORIZONTAL PIPE (WITH THE MACHINE IN VERTICAL ORIENTATION).**

RIGGING AND LIFTING THE LDSF

The LDSF frame can be lifted in any of the following configurations:

- individual sections (each section 1/4 of the frame)
- half-ring assemblies (each assembly consisting of 2 individual sections)
- fully assembled frame, with hinge.

Disassemble the frame into individual sections only for storage, or for moving it if necessary.

In This Chapter

SAFE OPERATION OF THE LDSF

RIGGING AND LIFTING THE LDSF

ASSEMBLING THE LDSF

SETTING UP THE LDSF ON THE PIPE

PARTING AND PARTING-BEVELING OPERATION

COUNTERBORING OPERATION

Removing the LDSF from the Pipe

When mounting the frame on the workpiece, you must have the LDSF fully assembled. Use the hinge and jack to spread the ring open to install it on in-line pipe.

Lift Attachments

Two types of lift attachments are provided with the LDSF.

• Use the lift eyes screwed into the top of the machine ONLY for lifting individual (1/4 ring) sections.



Figure 3-1. To lift an individual section, attach the rig to the lift eyes on top of the machine.

• Use the lift brackets mounted on the outside of the frame to lift half-ring assemblies, or the fully assembled frame.



Figure 3-2. Use the lift brackets on the side of the frame to lift the assembly machine.

• the top eye of the bracket is for lifting the machine in a horizontal orientation



Figure 3-3. Lift the machine horizontally as shown.

• the side eye of the bracket is for lifting the machine in a vertical orientation.



Figure 3-4. Lift the machine vertically as shown.

ASSEMBLING THE LDSF

Stand legs are supplied for assembling the LDSF frame on the floor to prepare it for mounting on the pipe. Three legs are provided for each individual section of the frame. Insert the legs into the holes in the bottom of the stationary ring when moving the sections to the assembly location.



Figure 3-5. Insert the stand legs into the bottom of the stationary ring.

The latches at the end of each section are stamped with a letter identifying the joints—A, B, C, and D. Assemble the sections so that the letters are matched up.



Figure 3-6. The photos show the joint letters stamped on the rotating ring (top) and stationary ring (bottom). Always line up the matching letters when assembling sections of the machine.

Chilling Street

1. Lift each individual section of the frame out of the storage crate. Insert the stand legs and set the sections down on the floor. Arrange the sections so that the joint letters are matched up.



Figure 3-7. Attach the rigging as shown to lift individual sections of the LDSF frame.

2. Remove the wood end caps from the ends of the sections.



Figure 3-8. Remove the screws to take the end caps off the ends of the sections.

3. At each joint, press the sections together to engage the dowel pins.



Figure 3-9. Push the sections together to close the split line. (There will be about a 1/2" gap between the sections until you tighten the latch bolts.)

4. On the stationary ring (underside of the machine), swing the latch bolts into place. Snug the nuts to hold the bolts in place.



Figure 3-10. Swing the latch bolts in the stationary ring into the slots, and snug the nuts to hold them in place.

5. On the rotating ring, swing the latch bolts into place. Snug the nuts to hold the bolts in place.



Figure 3-11. Swing the latch bolts in the rotating ring into the slots, and snug the nuts to hold them in place.

6. Tighten the nuts on the stationary ring latch bolts. The split line between the sections should close completely, with no gap between the sections.



Figure 3-12. Tighten the nuts on the stationary ring latch bolts to secure the sections together.

7. Tighten the nuts on the rotating ring latch bolts.



Figure 3-13. Tighten the nuts on the rotating ring latch bolts.

8. Attach the support block at each joint, and insert and tighten the 4 screws.



Figure 3-14. Install the support block at each split line and tighten the 4 screws.

SETTING UP THE LDSF ON THE PIPE

Attaching the Hinge and Jack

1. Attach the hinge to the LDSF stationary ring at the location with the holes provided.



Figure 3-15. Attach the hinge to the stationary ring.

2. Insert and tighten the two screws in each half of the hinge.



Figure 3-16. Insert and tighten the screws holding the hinge.

3. Remove the pins on the ends of the hinge and insert them through the eyes of the jack screws. (You may need to turn the jack screws to set the jack to the appropriate length.)



Figure 3-17. Mount the jack using the pins at the ends of the hinge.

Setting the Clamp Leg Positions

The LDSF clamps legs can be mounted in two positions:

- outer (standard) position for 82.5"-90" pipe diameter range
- inner position for 75"-82.5" pipe diameter range.

Use the following procedure to change the legs from the outer to the inner position.

1. Turn the adjustment screw on the clamp leg counterclockwise until you can remove the leg.



Figure 3-18. Turn the adjustment screw to advance the clamp leg all the way out.

2. Attach the cone spacer to the inner side of the stationary ring and tighten the screws.



Figure 3-19. Attach the cone spacer to the inside of the stationary ring.

3. Insert the leg through the cone spacer and press it all the way in. Turn the adjustment screw clockwise to engage the threads on the leg, and retract the leg for mounting the LDSF.



Figure 3-20. Insert the clamp leg through the cone spacer and turn the adjustment screw to thread it in.

Make sure you set all 12 clamp legs to the same position. You will not be able to mount the LDSF on the pipe correctly if the legs are not all the same.

Mounting the Machine

- **1.** Make sure the frame locking pins are inserted through the rotating ring.
- **2.** Loosen the nuts on the latch bolts at the joint opposite the hinge (both rotating and stationary rings). Swing the latches out of the slots.



You must remove the support block between the sections to access both latch bolts in the stationary ring.



Figure 3-21. Loosen the nuts on the latch bolts (stationary ring, top photo, and rotating ring, bottom photo) and swing them out of the slots.

- **3.** Loosen the nuts on the latch bolts at the hinge location (both rotating and stationary rings). Swing the latches out of the slots.
- **4.** Loosen, but do not remove, the two screws on the right side of the hinge assembly.



Figure 3-22. Loosen the two screws on the right side of the hinge to allow the screws to move in the slotted holes.

- **5.** At the joint opposite the hinge, turn the jacking screw to separate the ring sections. Turn the screw until the dowel pins are out of the holes. Retract the jacking screw completely.
- 6. At the hinge location, turn the jacking screw to separate the ring sections. Turn the screw until the dowel pins are out of the holes. Retract the jacking screw completely.





Figure 3-23. Turn the jacking screws to separate the sections at both split points.

7. Tighten the two screws on the right side of the hinge assembly.



Figure 3-24. Tighten the two screws to secure the hinge to the stationary ring.

8. Set the ratchet on the jack to retract the threaded rods (pulling the ends of the hinge together). Operate the jack to open the LDSF. Make sure the dowel pins separate from the holes at both split points.



Figure 3-25. Operate the jack to open the machine.

- **9** Open the LDSF far enough to mount it over the pipe.
- **10.** Rig the machine according to the instructions in "Rigging and Lifting the LDSF" earlier in this chapter.
- **11**. Lift the machine and remove the stand legs.
- **12.** Mount the machine over the pipe at the cutting location. Make sure the stationary ring and clamp legs are on the fixed (supported) side of the cut line.
- **13.** Reverse the ratchet on the jack. Operate the jack to close the machine on the pipe.
- **14.** On the split line opposite the jack, swing the latch bolts on the stationary ring into the slots. (Loosen the nuts if necessary.) Snug down the nuts to hold the latch bolts in place.



There will be about a 1/2" gap between the sections when you close the machine. The latch bolts will pull the sections together to close the gap.



Figure 3-26. Swing the latch bolts into place in the slots.

- **15.** On the split line at the jack location, swing the latch bolts on the stationary ring into the slots. (Loosen the nuts if necessary.) Snug down the nuts to hold the latch bolts in place.
- **16.** Loosen, but do not remove, the two screws on the right side of the hinge assembly.



Figure 3-27. Loosen the two screws on the right side of the hinge to allow the screws to move in the slotted holes.

17. On the split line opposite the jack, tighten the nuts on the stationary ring latch bolts. The split line between



the sections should close completely, with no gap between the sections.

Figure 3-28. Tighten the nuts on the latch bolts.

- **18.** On the split line at the hinge, tighten the nuts on the stationary ring latch bolts. The split line between the sections should close completely, with no gap between the sections.
- **19.** Tighten the two screws on the right side of the hinge assembly.



Figure 3-29. Tighten the two screws to secure the hinge to the stationary ring.

20. Attach the support block to the stationary ring at each joint. Insert and tighten the 4 screws holding the block.



Figure 3-30. Attach the support block at the joint and tighten the 4 screws.

21. Swing the latch bolts in the rotating ring into the slots at both split lines. Tighten the nuts to secure the latch bolts.



Figure 3-31. Swing the latch bolts into the slots and tighten the nuts.

- **22**. Tighten all latch bolt nuts securely.
- **23.** Turn the adjustment screws on the clamp legs in the center of each section (4 legs at 90° angles) until the clamp feet contact the pipe.



Figure 3-32. Turn the clamp leg adjustment screws to set the clamp feet against the pipe.

- **24.** Measure the clearance between the stationary ring and the pipe at each clamp leg position, and adjust the legs as necessary so that the machine is centered on the pipe.
- **25.** Tighten the 4 center clamp legs to 30 lb-ft. Check the clearance at each location again, and adjust if necessary.
- **26**. Tighten the other 8 clamp legs to **30 lb-ft**.
- **27.** Tighten the 4 center clamp legs to **60 lb-ft**, then tighten the other 8 legs to **60 lb-ft**.
- **28.** Tighten the 4 center clamp legs to **90 lb-ft**, then tighten the other 8 legs to **90 lb-ft**.
- **29.** Remove the rigging from the machine.

Mounting the Drive Motor Assembly

The motor assembly is mounted to the stationary frame as a complete unit.



Recommended tightness on the clamp legs is 90 lb-ft. Tighten all legs in steps, 30 lb-ft at a time, until they are at 90 lb-ft.



Figure 3-33. The photo shows the drive mounting location on the LDSF frame. The three screws in the drive assembly go into the three holes on the frame.



Figure 3-34. The photo shows the hydraulic drive assembly.



Figure 3-35. Attach the drive assembly to the stationary ring.



Figure 3-36. Tighten the screws holding the drive assembly.

PARTING AND PARTING-BEVELING OPERATION

Setting up the Slides

Offset Parting Setup

For parting (straight cutoff) operation, use a parting tool in each slide. Use the large spacer blocks to mount the tools in the slide, as described below.

1. In the first slide, set the large spacer block into the tool holder in the **low** orientation (with no gap at the side of the block). Tighten the mounting screw into the spacer block.

Screw goes into hole in spacer block

No gap with block in low orientation



Figure 3-37. Put the spacer block in the tool holder in the low orientation (no gap between block and holder).

2. In the second slide, set the large spacer block into the tool holder in the **high** orientation (with a gap at the side of the block). Tighten the mounting screw into the spacer block.



Figure 3-38. Put the spacer block in the tool holder in the high orientation (with a gap between the block and holder).

- **3.** In each slide, install a parting tool on top of the spacer block.
- **4**. Install the tool cover by sliding it over the tool holder.



Figure 3-39. Slide the tool cover onto the tool holder and position it flush at the front.

5. Set the tool back in the holder and tighten the screw in the tool cover. You will adjust the tool position after mounting the slide to the machine.

6. Turn the starwheel on both slides clockwise to fully retract the slide.

Parting-Beveling Setup

For parting and beveling, use a parting tool in one slide and a beveling tool in the other slide. Either slide can be used for parting or beveling.

1. In the first slide, set the large spacer block into the tool holder in the **low** orientation (with no gap at the side of the block). Tighten the mounting screw into the spacer block.

Screw goes into hole in spacer block

No gap with block in low orientation



Figure 3-40. Put the spacer block in the tool holder in the low orientation (no gap between block and holder).

- **2.** Install a parting tool on top of the spacer block. Install the tool cover by sliding it over the tool holder.
- **3.** Set the tool back in the holder and tighten the screw in the tool cover. You will adjust the tool position after mounting the slide to the machine.
- **4.** In the second slide, set the small spacer block into the tool holder, and tighten the mounting screw into the spacer block.



Figure 3-41. Use the small spacer block for installing a beveling tool.

- **5.** Install a beveling tool in the gap next to the spacer block.
- 6. Set the tool back in the holder and tighten the set screw in the side of the tool holder. You will adjust the tool position after mounting the slide to the machine.
- **7.** Turn the starwheel on both slides clockwise to fully retract the slide.

Mounting the Slides on the LDSF

1. On both slides, turn the jacking screw so that the end plate is all the way forward. Snug the screw, but do not over-tighten it.



Make sure the slides are fully retracted before mounting them. See "Setting up the Slides" on page 44.



Figure 3-42.

- **2.** Install the mounting blocks for both slides on the rotating ring. Leave the screws loose so you can mount the slide.
- **3.** Slide the base plate of the slide beneath the mounting blocks.



Figure 3-43. Attach the mounting blocks loosely to the rotating ring, and mount the slide between the blocks.

4. Push the slide forward until the tracking wheel is against the pipe. Snug down the screws in the mounting block just tight enough to hold the slide. It will

need to move when you run the machine to set the slide positions.

- **5.** Remove the frame locking pins from the rotating ring and put them in their storage locations on the side of the machine.
- 6. When you have both slides mounted, connect the hydraulic lines to the machine and turn on the HPU.
- 7. Operate the LDSF slowly through one complete rotation. As the tracking wheel on each slide travels over the surface of the pipe, it will push the slide back so that it is in position to contact the pipe at the high point (the location where the clearance is least).
- **8.** Securely tighten the screws in the slide mounting blocks to hold the slides in position.



Figure 3-44. Tighten the screws in the slide mounting blocks.

- **9.** Turn the jacking nuts on both slides back all the way to release the springs for operation.
- **10.** Loosen the tool set screws in both slides, and move the tools forward until they are about 1/16" from the pipe. Tighten the set screws.

Mounting and Configuring the Trip

1. Mount the trip assembly to the mounting location on the stationary ring.



Figure 3-45. Mount the trip to the stationary ring.

- 2. Loosen the trip lock lever, and push the trip all the way in against the machine. Tighten the trip lock lever.
- **3.** Using the drive motor, rotate the frame to position one of the starwheels over the trip assembly.
- **4.** Loosen the trip adjustment knob, and slide the trip toward or away from the frame to position it beneath the starwheel. Tighten the trip adjustment knob.
- **5.** Loosen the trip lock lever to release the slide to the disengaged position. (The slide is spring-loaded and will disengage when the lever is loosened.)
- 6. Tighten the trip lock lever. Leave the trip disengaged until you are performing the cut.

Double-Trip Setup

You can use two trips to double the feed rate. Install a second trip at the opposite location on the stationary ring, and configure it as described above.

Performing the Cut

- **1.** Turn on power at the HPU. Set the operating pressure to 2000 psi.
- **2.** Remove both frame locking pins from the rotating ring, and put them in their "parking" holes in the stationary ring.



Figure 3-46. Remove the frame locking pins and put them in the parking holes in the stationary frame.

- **3.** Make sure that the trip is disengaged.
- **4.** Turn on the hydraulic power and slowly operate the machine through one rotation to check clearances and make sure the slide tracking wheels are following the pipe surface. Stop the machine.
- **5.** Loosen the trip lock lever and push the trip in to engage it.
- 6. Start the machine and set the flow to 14 gpm at the HPU. Make sure the starwheels are striking the trip.
- 7. Operate the machine until the tools begin cutting the pipe. Use of coolant is recommended for better cutting performance and to increase tool life.
- **8.** Adjust the speed as necessary for optimum cutting performance. Make sure both slides are advancing and both tools are cutting.
- **9.** Operate the machine until the cutting operation is complete. Turn off power at the HPU.
- **10.** Turn the starwheels on both slides to retract them.



Recommended hydraulic settings are 14 gpm flow at 2000 psi pressure.



Stand clear of the LDSF while it is operating. There are pinch points between moving components that can cause serious injury.



Counterbore slide operation with the LDSF is intended only for use on a horizontal pipe (with the machine in vertical configuration). Operating the counterbore slide with the machine mounted horizontally is not safe for the operator.

COUNTERBORING OPERATION

The counterbore slide mounts to the tool holder on the standard LDSF slide. Use only one slide when counterboring. Disengage or remove the trip when counterboring.

If you have performed a parting or parting/beveling operation, the LDSF is correctly positioned on the pipe for counterboring. Do not move the LDSF before performing the counterbore.

NOTE: Counterbore slide operation with the LDSF is intended only for use on a horizontal pipe (with the machine in vertical configuration). Operating the counterbore slide with the machine mounted horizontally is not safe for the operator.

Mounting the Slide and Tooling

1. Insert the tool bit into the holder of the counterbore slide. Several tool configurations are available; see examples in the figures below.



Figure 3-47. Mount the appropriate tool in the counterbore slide.

2. If you are going to counterbore at an angle, loosen the nut on the counterbore slide pivot and set the slide at the desired angle. Tighten the pivot nut.



Figure 3-48. Loosen the pivot screw to set the counterbore slide angle.

- **3.** Install and configure **one** LSDF slide as described in "Mounting the Slides on the LDSF" above.
- **4.** Set the base of the counterbore slide in the tool holder on the LDSF slide. Do not tighten it in place yet; you will need to move it when setting the position.



Figure 3-49. Mount the counterbore slide in the tool holder on the LDSF slide.

- Turn the starwheel on the LDSF slide to position the counterbore slide at the required position over the pipe end. Turn the counterbore slide knob as necessary to align the tool bit with the pipe.
- 6. Tighten the set screw in the tool holder to secure the counterbore slide in place.

Performing the Counterbore

- **1.** Turn the knob on the counterbore slide to advance the tool close to the pipe surface.
- **2.** Make sure that the trip is disengaged. It is recommended to remove the trip when counterboring.
- **3**. Turn on power at the HPU.
- **4.** Start the machine. Turn the counterbore knob each rotation of the LDSF to feed the slide.
- **5.** Continue feeding the counterbore slide as the machine operates. Use of coolant is recommended for better cutting performance and longer tool life.
- 6. Stop the machine periodically to check and measure the counterbore.
- **7.** When the counterbore is complete, turn off hydraulic power.
- **8.** Retract the counterbore slide, and remove it from the tool holder of the LDSF slide.

REMOVING THE LDSF FROM THE PIPE

- **1.** Operate the machine to align the split lines of the rotating ring with the matching split lines of the stationary ring (A to A, B to B, etc.). Stop the machine with the split lines on both rings lined up.
- **2.** Insert the 2 frame locking pins through the rotating ring.
- **3**. Turn the starwheels on both slides to retract them.
- **4.** Loosen the screws in the slide mounting brackets and remove the slides from the LDSF.

- **5**. Remove the drive assembly from the LDSF.
- 6. Rig the LDSF and make sure the lifting device is holding it securely before you loosen the clamp legs.
- **7.** Turn the adjustment screws on the clamp legs to loosen the legs. Retract the legs all the way.
- **8.** Remove the support blocks from the stationary ring at the hinge location and the opposite location where the machine will be split.
- **9.** Loosen the nuts on the latch bolts at the joint opposite the hinge (both rotating and stationary rings). Swing the latches out of the slots.
- **10.** Loosen the nuts on the latch bolts at the hinge location (both rotating and stationary rings). Swing the latches out of the slots.
- **11.** Loosen, but do not remove, the two screws on the right side of the hinge assembly.
- **12.** At the joint opposite the hinge, turn the jacking screw to separate the ring sections. Turn the screw until the dowel pins are out of the holes. Retract the jacking screw completely.
- **13.** At the hinge location, turn the jacking screw to separate the ring sections. Turn the screw until the dowel pins are out of the holes. Retract the jacking screw completely.
- **14.** Tighten the two screws on the right side of the hinge assembly.
- **15.** Set the ratchet on the jack to retract the threaded rods (pulling the ends of the hinge together). Operate the jack to open the LDSF. Make sure the dowel pins separate from the holes at both split points.
- **16.** Replace the wood end caps on each of the sections.
- **17**. Open the LDSF far enough to remove it from the pipe.
- **18.** Lift the LDSF from the pipe and move it to a location where you can set it down. Install the stand legs and set the LDSF on the floor.
- **19.** If you are finished with the machine, disassemble it for storage.



























DESCRIPTION CAP, CLAMP LEG END SCREW, CLAMP LEG WASHER, THRUST SPACER, CLAMP LEG COLLAR, 30mm CLAMP ON	
PART NUMBER 12-042-0202 12-042-0205 12-042-0206 12-042-0206 12-042-1986	
11EM NO. 22 33 55	

						∞)	(A RELEASE FOR PRODUCTION 11/29/2012 MWG 6.00 Knightsbridge Parkway Lincolnshire, IL 60069 REV. DESCRIPTION DATE AR. Arr. <	MUC MWC KNP Z:3 E11 wOLG WREAKNER PARADER (N1 70) DORAGE RELAKIOL IN DORAGE RELAKIONALI IN DORAGE RELAKIONALI IN DORAGE RELAKIOL IN DORAGE RELAKIOL IN DORAGE RELAKIOLINI DORAGE RELAKIOLINI DORAGE RELAKIOLINI DORAGE RELAKIONALI IN DORAGE RELAKIONALI I
QTY.	-	-	-	2	2	-	-	-	-	(1)		
DESCRIPTION	SHAFT, ECCENTRIC V-ROLLER	SCREW, ECCENTRIC LOCKING	ROLLER, V-GROOVE	SEAL, 1.563 × 2.066	BEARING, .9843 x 2.0472 x .5906 BALL	3/8-24 X 3/4 LONG SSS	WASHER, 1" HEAVY DUTY MACHINED FLAT	NUT, M24 x 1.5mm	7.5 TO 15 PSI - 1/8" NPT PRESSURE RELIEF VENT	T-LLBS, LOOSEN THEN SET TO 180 IN-LB FINAL TENSION		
PART NUMBER	12-042-0040	12-042-0041	12-042-0042	12-042-0044	SKF - 7205 BE	91375A646	12-042-1990	12-042-1989	1093K2	BRICATION TABLE IN		
ITEM NO.	-	2	3	4	5	9	7	∞	6	NOTE: TIGHTE SEE LU		







NO.	PART NUMBER	DESCRIPTION	QTY.
_	6205-2RSL	BEARING	4
7	12-042-0401	BEARING HOUSING	2
m	12-042-0403	MOUNTING BRACKET, DRIVE	-
4	12-042-0404	MOUNTING BRACKET, DRIVE	2
5	12-042-0405	PLATE, PINION HOUSING	-
9	12-042-0410	RETAINER, GEAR	7
~	12-042-0396	SCREW, CAPTIVATED	т
ω	12-042-1971	SHCS, M8 x 1.25mm x 20mm LNG.	10
6	12-042-1995	WASHER, M20 THICK	e
10	12-042-1972	SSS, M10 x 1.5mm x 20mm LNG.	2
[]	12-042-1968	SHCS, 3/8-16 × 1" LNG.	∞
12	12-042-1970	SHCS, M12 x 1.75mm x 30mm LNG.	т
13	12-042-0409	SHAFT	2
14	91847A525	JAM NUT, 1/2-20	2
15	12-042-1969	FHCS, M8 x 1.25mm x 25mm LNG.	5
16	EATON 101-1014	HYDRAULIC MOTOR	7
17	12-042-0400	GEAR, PINION	2
18	TLP-5083	LOCATING PIN	2
19	12-042-1973	FHCS, M8 x 1.25mm x 22mm LNG.	7
20	12-042-0406	COVER, DRIVE GEAR	1
21	96717A230	KEY, 6mm SQ. x 36mm LNG.	2
22	CLM-100-BND	DOWEL, M10 BULLET NOSE	2
23	99642A163	SSS, M10 x 1mm x 20mm LNG.	2
24	91415A215	NUT, M10 x 1mm	2



















ItemNo. Part Number Descretrion 1 2.042.039 BOLL 13C0 Mil 2 Somm Mic. 2 1.2042.055 BOLL 13C0 Mil 2 Somm Mic. 3 1.2042.055 BOLL 13C0 Mil 2 Somm Mic. 6 1.2042.055 BOLL 13C0 Mil 2 Somm Mic. 7 1.2042.055 BOLL 13C0 Mil 2 Somm Mic. 8 0.11.550 Washer, ADD Hick 9 0.12550 Washer, ADD Hick 1 1 Vasher, Subr. 11 X 201C. 9 9212551 Washer, ADD Hick 13 918286442 Mil, MIX 201THICK 13 918286442 Mil, MIX 201C.	
ITEM NO. PART NUMBER 1 1 2.042-0650 2 12-042-0650 3 3 12-042-0650 4 1 12-042-0650 5 3 12-042-0650 5 3 12-042-0650 5 4 12-042-0650 6 7 1 12-042-0650 8 60-1034 9 9 60-1035-000 11 11 14 91828-4420 12 91828-4420 11 13 91828-4420 11 9 60-1235-00 11 9 91828-4420 11 9 91828-4420 11 9 91828-4420 11 9 91828-4420 11 9 91828-4420 11 9 91828-4420 11 13 91828-4420 91828-4420 14 938-94400 91828-4420	ACC Knightsbridg ACC Knightsbridg Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Inconshiev Incons
	EP.FOR \$/13/2013 MM LCTION 5/13/2013 MM PPTON DATE AP VISION HISTORY Exercise consultant Exercise consultant VESION HISTORY Exercise consultant Exercise consultant Premior Interaction consultant Exercise consultant VESION Exercise consultant Exercise consultant VESION Exercise consultant Exercise consultant VISION Exercise consultant Exercise consultant VISION Exercise consultant Exercise consultant VISION Exercise consultant Exercise consultant
	A RELEAS FV. DESCE EV. DESCE BIL

QTY.			-	_	-	-	-	-	-	-		-			-	_		_	4 (7		2	2	m	-	4		- ~	1	- 7			ay		2:5	OF 1	REV.
DESCRIPTION	KIT, CLAMP LEG KEY WASHER	KEY, CLAMP LEG	HOUSING, PIVOT	BAR, C'BORE	TUBE, HOUSING	SCREW, FEED	NUT	HUB	PLATE, TUBE RETAINING	PLATE, PIVOT SLIDE LEFT	BLOCK, PIVOT SLIDE LOCKING	BLOCK, PIVOT SLIDE MOUNTING	NUI, PIVIOI LOCK BI ATE BIVIOT SI IDE BICHT	KNOB, PIVOT FEED	SCREW, TOP LOCK	BUSHING, 5/8" × 1/2" × 3/8" LNG.	RING, 1.750 x .068 EXTERNAL RETAINING	RETAINING RING, INTERNAL	THRUST WASHER	THRUST NEEDLE ROLLER BEARING	WASHER, 1/2" WAVE	NUT, M8 x 1.25 NYLOCK	SHCS M5 x 22 MM LG	SHCS, M8 x 1.25mm x 12mm LNG.	SHCS, M8 × 1.25mm × 20mm LNG.		HHCS, MI0 X I .5mm X 90mm LNG. WASHEP MI 2		SSS-SS_M5 x_8mm x_10mm1NG	BOLT, SHOULDER M10 × 70mm LNG.		E.H. WACHS	APR. APR. www.ehwachs.com	TITLE SLIDE, PIVIOT	DRAWNBY APPROVED BY SCALE	± ±000 DATE DATE SHEET I νL ± 000 5-14-13 DATE 1 1	DUT ME BIE DWG. NO. 12-042-4413-00
PART NUMBER	12-042-0208	12-042-0209	12-042-1401-00	12-042-1402-00	12-042-1403-00	12-042-1404-00	12-042-1406-00	12-042-1407-00	12-042-1410-00	12-042-1411-00	12-042-1413-00	12-042-1414-00	12-042-1415-00	12-042-1418-00	69-400-44	AA-628-7	RST-175	Smalley WH-98	TRB-815	5909K31	90134A033	90576A117	91290A248	91290A416	91290A426	71272A110	91310A655 91455A150	91595A640	92605A233	92981A309			TION 5/14/2013	ISION HISTORY	FICIFIED: TOLERANCES: INCHED: FRACTIONS ±1/32 INCHES. ON EPLACE DECIMAL	DARUS (WI 17-01) TWO PLACE DECIMAL IFIED ON DRAWING. THREE PLACE DECIMA ANG. ANGULAR ±15 MIN.	REPORMATION CONTAINED IN THE DRAWING I REPRODUCTION IN PART OR AS A WHOLE WITH 5 PROHIBITED.
NO.	-	2	ო	4	5	9	7	∞	6	10	=	12	<u></u>	15	16	17	18	16	50	2]	22	23	24	25	26	77	28	ý C	86	32			RELEASEL PRODUC DESCRIP	REV	LESS OTHERWISE SF LL DIMENSIONS ARE IN	WORKMANSHP SLAN O ALLITEMS NOT SPEC DO NOT SCALE DRAV	ND CONFIDENTIAL: THE OF E.H. WACHS, ANY SION OF E.H. WACHS I
																															(26)						